


DESCRIPTION

STANDARDIZED GEAR UNITS FOR MINING APPLICATIONS

MHP.2 - ...




mark option required with

- 1 breather plug
- 2 dust proof breather plug
- 3 fan cooling: 1 or 2 fans possible
- 4 oil filler plug
- 5 dipstick
- 6 gear unit inspection covers
- 7 dual grease purgable seals and Oil-Guard™ dynamic drain back at the high speed shaft
- 8 flippable gear unit
- 9 backstop
- 10 scoop M5
- 11 motorbase M1
- 12 normal solid shaft
- 13 hollow shaft with shrink disc connection
- 14 hollow shaft with keyway
- 15 draining plug
- 16 dual grease purgable seals at the low speed shaft
- 17 standard tilting of 3° in all directions

DESCRIPTION

STANDARDIZED GEAR UNITS FOR MINING APPLICATIONS

MHR.2 -...



- mark option required with
- 1 breather plug
 - 2 dust proof breather plug
 - 3 oil filler plug
 - 4 dipstick
 - 5 gear unit inspection covers
 - 6 fan cooling: 1 fan possible
 - 7 dual grease purgable seals and Oil-Guard™ dynamic drain back at the high speed shaft
 - 8 flippable gear unit
 - 9 lantern housings for flexible and hydrodynamic coupling
 - 10 backstop
 - 11 scoop M8
 - 12 motorbase M3
 - 13 normal solid shaft
 - 14 hollow shaft with shrink disc connection
 - 15 hollow shaft with keyway
 - 16 draining plug
 - 17 dual grease purgable seals at the low speed shaft
 - 18 standard tilting of 3° in all directions